Document ID: 2578447 Page 1 of 1

**Document ID: 2578447** 

# **#PI0368: Creaking or Squeaking Noise from Front End While Turning Steering Wheel in Cold Ambient Temperatures - (Feb 9, 2011)**

**Subject:** Creaking or Squeaking Noise from Front End While Turning

**Steering Wheel in Cold Ambient Temperatures** 

Models: 2010-2011 Cadillac SRX



#### **Condition/Concern**

Some customers may comment that they hear a creaking or crunching noise from the front of the vehicle when they turn the steering wheel. The noise may be more noticeable when the ambient temperatures falls below 4°C (40°F).

The upper strut mount spring plate may come in contact with the strut mount bearing. When the two pieces meet they create a squeaking noise. The front strut mount noise can be identified by moving the steering wheel while the vehicle is in Park.

#### **Recommendation/Instructions**

Replace both front upper strut mounts with revised designed parts. Follow the published SI repair procedures to install the strut mounts.

## **Parts Information**

Part Number	Description	Qty
20999167	Mount Assembly, Front Suspension Strut	

### **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
E3853	Strut, Strut Component, or Spring Replacement - Both Sides	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



© 2011 General Motors. All rights reserved.